




SERVICE BULLETIN

98- T3.05

DATE: 2/9/98

MODEL CONCERNED: All Tractors

SERIAL NUMBERS: FROM 80326.....




Printed Circuit Boards

The new printed circuit board operates in exactly the same way as before. However they are not retro-fit as the fixings are different.

Standard tractor PCB. All Tractors before

Serial No. 80326.....


Part No. 26817000



New layout for all

tractors (inc. A20/50)


a)	M5captive nut	04928600
b)	PCB support bracket	302002500
c)	PCB	(as shown)
d)	PCB Cover	1480032000
e)	Retaining Screw	028000500



Electric Actuator Lift tractors (inc.
A20/50)

after Serial No. 80326.....

Part No. 448001900



Standard tractor (non-HE)
after Serial No. 80326.....

Part No. 448001800

Please contact COUNTAX Service Department for any further information.